


Parts



(Note: max. pull force <100N)

Instruction

1 Move

2 Install components on the cable assembly

3 Screw on, DO NOT TIGHTEN !

4

5

6 Tighten backshell

7 Tighten nut

While the information has been carefully compiled to the best of our knowledge, nothing is intended as representation or warranty on our part and no statement herein shall be construed as recommendation to infringe existing patents. In the effort to improve our products, we reserve the right to make changes judged to be necessary.

Draft	Date	Approved	Date	Rev.	Engineering change number	Name	Date
Huppenberger	04.02.2014	S. Gramsamer	13.02.2014	200	14-v104	Markus Wallner	13.02.2014

Rosenberger Hochfrequenztechnik GmbH & Co. KG P.O.Box 1260 D-84526 Tittmoning Germany www.rosenberger.de				Tel. : +49 8684 18-0 Fax. : +49 8684 18-499 Email : info@rosenberger.de			Page 1 / 1
--	--	--	--	---	--	--	---------------